

2841
2842

MF3-12 / MF6-20

MF
DIN 13

>2841
(2301 + 2501)



>2842
(2301 + 2501)



Ref.	Machos y cojinetes Tarauds et filières Taps and bearing	Volvedores Porte-filières Tap wrench	Giramachos nº Tourne-à-gauche nº Tap turner nº	Carraca nº Cliquet nº Ratchet nº
2841	M3x0,35-4x0,50-5x0,50-6x0,75-8x0,75 8x1,00-10x1,00-12x1,50	20x5-25x9-30x11-38x10	1 - 2	1
2842	M6x0,75-8x0,75-8x1,00-10x1,00-12x1,00-12x1,50 14x1,25-14x1,50-16x1,50-18x1,50-20x1,50	20x7-25x9-30x11-38x10-45x14	1 - 3	1